


DATSUN 240Z Parts - Interior part



DATSUN 240Z Parts - Interior part



10


DATSUN 240Z Parts - Interior part



11




DATSUN 240Z Parts - Interior part and emblems



DATSUN 240Z Parts - Instrument



DATSUN 240Z Parts - Interior part



20



DATSUN 240Z Parts - Suspension



DATSUN 240Z Parts - Bumpers




DATSUN 240Z Parts - Bumpers



DATSUN 240Z Parts - Electrical



DATSUN 240Z Parts – Cooling System



DATSUN 240Z Parts – Locker




29



28




DATSUN 240Z Parts – Engine Bay



DATSUN 240Z Parts – Fuel system



DATSUN 240Z Parts – Fuel system




DATSUN 240Z Parts – Fuel system

36

Fuel Tank

DATSUN 240Z Parts – Header & exhaust




DATSUN 240Z Parts – Header & exhaust



DATSUN 240Z Parts – Lighting



39



40

DATSUN 240Z Parts – Lighting



41

DATSUN 240Z Parts – Lighting



42




DATSUN 240Z Parts – Exterior



43



DATSUN 240Z Parts – Suspension & Exterior



DATSUN 240Z Parts – Exterior

47

Doors

DATSUN 240Z Parts – Exterior

48

Hood

DATSUN 240Z Parts – Brake



49

Front Brake set

50

Rear Brake set

DATSUN 240Z Parts – Clutch



DATSUN 240Z Parts – Cooling system

52

Radiator

DATSUN 240Z Parts – Instrument



DATSUN 240Z

Parts – Price list

Category	Reference	Qty	Description	Unit Price New (MSA) - USD	Status	Discount	Final Price USD	MXN (1USD = 16 MXN)
Interior Part	1	1	Shift Knob, Manual Transmission	150	used	50%	75	1,200
Interior Part	2	2	Window Crank, Black + Crank protector	34	new	90%	61	979
Interior Part	3	1	Window Crank, Black	32	used	50%	16	256
Interior Part	4	1	Armrest, Left	33	new	90%	30	475
Interior Part	5	1	Armrest, Right	33	new	90%	30	475
Interior Part	6	2	Door handle chrome finisher	30	restored	70%	42	672
Interior Part	7	2	Door handle chrome finisher	30	used	50%	30	480
Interior Part	8	2	Interior Door Handle + Trims	62	used	50%	62	992
Interior Part	9	2	Doors blockers		used	50%	10	160
Interior Part	10	1	Window system LH & RH	100	restored	70%	70	1,120
Interior Part	11	2	Seat Belt	56	used	50%	56	896
Interior Part	12	2	Fuse Box covers	75	used	50%	75	1,200
Interior Part	13	1	Dash center vent	55	new	90%	50	792
Interior Part	14	1	Cigar	15	used	50%	8	120
Emblem	15	1	Roof Emblem	49	used	50%	25	392
Instrument	16	2	Speedometer	169	used	50%	169	2,704
Instrument	17	2	Tachometer	253	used	50%	253	4,048
Instrument	18	2	Amp / Fuel gauge	205	used	50%	205	3,280
Instrument	19	1	Oil Pressure / Water Tempature gauge	205	used	50%	103	1,640
Interior Part	20	2	Interior hatch		restored		50	800
Suspension	21	4	Stock springs		restored		80	1,280
Bumpers	22	2	Front Bumper brackets	110	restored	70%	154	2,464
Bumpers	23	1	Rear Bumpers additional guards		used		80	1,280
Bumpers	24	2	Rear Bumpers guards Left & Right	70	used	50%	70	1,120
Bumpers	25	2	Front Bumpers guards Left & Right	150	used	50%	150	2,400
Electrical	26	1	Washer Tank & motor	250	used	50%	125	2,000
Cooling System	27	1	Radiator overflow tank	15	used	50%	8	120
Locker	28	1	Hood locker		used		15	240
Locker	29	1	Glove box lock	65	used	50%	33	520
Engine Bay	30	1	Horn		used		20	320
Engine Bay	31	1	Engine inspection light	32	used	50%	16	256
Fuel system	32	1	Mechanical Fuel pump & tube	66	used	50%	33	528
Fuel System	33	1	Choke Cable	400	used	50%	200	3,200
Fuel system	34	1	Pair of S.U. Carburator	680	used	50%	340	5,440
Fuel system	35	1	Stock Manifold		used		50	800
Fuel system	36	1	Fuel Tank	454	restored	70%	318	5,085
Header & Exhaust	37	1	Stock Header		used		80	1,280
Header & Exhaust	38	1	Performance 3+2 Header + exhaust line	235	new	90%	212	3,384
Lighting	39	2	Turn signal Assembly	120	used	50%	120	1,920
Lighting	40	4	Marker Light	60	used	50%	120	1,920
Lighting	41	1	Tail Light set	550	used	50%	275	4,400
Lighting	42	1	Headlight set & trims	250	used	50%	125	2,000
Exterior	43	2	Mirrors	115	used	50%	115	1,840
Suspension	44	1	Stock front sway bar		used		50	800
Exterior	45	2	Stock front towing hook		restored		20	320
Exterior	46	1	Stock rear towing hook		restored		10	160
Exterior	47	2	Doors		restored		250	4,000
Exterior	48	1	Hood	445	restored	60%	267	4,272
Brake	49	1	Stock Front brake set incl. Dics		used		200	3,200
Brake	50	1	Stock rear brake set incl. Drums		used		200	3,200
Clutch	51	1	Stock flywheel + standard clutch		used		150	2,400
Cooling System	52	1	Radiator	299	used	50%	150	2,392
Instrument	53	1	Speedometer cable	90	used	50%	45	720